

6/2011

Mercedes-Benz MHI Approved Phones

Handset Model	Carrier	Software Level Tested	Adapter
Apple iPhone	AT+T	v1.0.2, v1.1.1, v1.1.2, v1.1.3, v1.1.4, v2.0, v2.0.	B67875878
Apple iPhone 3G	AT&T	SW2.2	
Apple iPhone 3GS	AT&T	SW3.0	
Apple iPhone 4	AT&T	SW4.0.1	
Blackberry 7250	Verizon	V4.0.0.204	
Blackberry 7290	Cingular/ T-Mobile	V4.0.2.32	
Blackberry 7100g	Cingular /T-Mobile	V4.0.0.219	
Blackberry 8703e	Verizon	4.1.0.344	
Blackberry 8700g	T-Mobile	4.1.0.346	
Blackberry 8700c	Cingular	4.1.0.377	
Blackberry 8800	Cingular	V4.2.1.72	
BlackBerry Curve 8300	AT&T	4.2.2.89 2.4.0.39	
BlackBerry 8520	AT&T	4.6.1.314	
BlackBerry Curve 8310	AT&T	4.2.2.170 , 4.2.2.184	
BlackBerry Flip 8220	T-Mobile	v4.6.0.160	
BlackBerry Bold 9000	AT&T	v4.6.0.167	
BlackBerry Bold 9650	Verizon	5.0.0.732	
BlackBerry 9700	AT&T	5.0.0.780	
BlackBerry 9530 Storm	Verizon	v4.7.0.75	
Blackberry 9800 Torch	AT&T	6.0.0.201	
Blackberry 9780 Bold	T-Mobile	6.0.0.285	
BlackBerry Curve 9300	AT&T	6.0.0.526	
BlackBerry Curve 9330	Verizon	V6.0.0.431	
BlackBerry 8900 Javelin	AT&T	v4.6.1.101	
BlackBerry 8830	Verizon /Sprint	4.2.2.66	
BlackBerry 8120	At&T/T-Mobile	4.3.0.91	
BlackBerry 8110	AT&T	4.3.0.93	
BlackBerry Tour 9630	Verizon	4.7.1.40	
Kyocera Strobe K612B	Alltel	SL1.0.00	
LG VX5500	Verizon	VX550V02	
LG versa VX9600	Verizon	VX960V02	
LG VX8100	Verizon	T81VZV05	
LG Chocolate VX8500	Verizon	T85VZ03	
LG VX9800	Verizon	T98VZV01	
LG VX 8800 Venus	Verizon	VX880V02	
LG Chocolate 3 VX 8560	Verizon	VX8560V05	
Motorola A455 Rival	Verizon	RUSH01_01.29.15P	
Motorola VE 20	Sprint	VEGAS2_00.60.00R	
Motorola V950	Sprint	WATER2_00.59.01P	
MB Motorola V710	Verizon	MB proprietary SW	
Motorola E815	Verizon	1.17.03, 01.1E.00	
Motorola V3c	Verizon	01.0F.03, 01.15.04	
Motorola V3c	Alltel	GATW_04.06.00R	
Motorola V3m	Verizon	NEWC_01.05.0A, NEWC_01.09.02	
Motorola V325i	Verizon	MLNBT1_01.07.00R	
Motorola RAZR ² V9m	Alltel	SPARK0_X_02.0B.09P	
Motorola RAZR ² V9m	Verizon	PARS_01.15.0D	
Motorola RAZR ² V9	AT&T	U_9C.13.37R_1	
Motorola K1m	Verizon	24.1_00.25.0C	
Motorola Q	Verizon	04.08.04P, 06.07.03P, 06.0B.11P	
Motorola Q9m	Verizon	C_03.20.0EP	
Motorola RAZR V3	Cingular /T-Mobile	0E.42.09R, 0E.42.0ER, 0E.40.57R, 0E.41.C3R_B, 0E.C0.15R, 0E.42.15R	
Motorola V3i	Cingular	R47A_G_08.D9.3DR	
Motorola V3t	T-Mobile	R3443U5_G_0E.C8.0DR	
Motorola ROKR E1	Cingular	30.34R_A	
Motorola V330	T-Mobile	8.18.1DR	
Motorola PEBL U6	T-Mobile	08.83.76R, 08.83.76R_A	
Motorola RIZR Z3	T-Mobile	R452B_G_08.01.02R	
Motorola V551	Cingular	8.18.16R_OA	
Motorola V557	Cingular	08.28.3DR_A3, 08.28.40R	
Motorola SLVR L7	Cingular	08.C4.1ER, 08.C4.25R	
Motorola V3xx	Cingular	R26111LD_U_96.71.95R	
Motorola K1	Cingular	R4527_G_08.42.0BR_A	
Motorola Rokr Z6	Verizon	PARS_01.16.0C	
Motorola KRAVE ZN4	Verizon	BLAZE1_01.19.0AP	
Motorola ZINE ZN5	T-Mobile	R6637_G_81.11.17R_128	
Motorola W755	Verizon	COOL01_00.30.08P	
Motorola Vu30	Verizon	CHARL1_01.30.06P	
Nokia 5300	T-Mobile	V05.02	
Nokia 6133	T-Mobile	V05.23	
Nokia 6102i	Cingular	4.63	
Nokia 6555	AT&T	V03.31	
Palm Centro	Sprint	CENTRO-1.00	
Samsung Roque U960	Verizon	V. u960.CG022	
Samsung Jack	AT&T	CE OS 5.2.20293 Build 20293.1.3.10	
Samsung M800	Sprint	ES.M800 BH 29	
Samsung U470 Juke	Verizon	u470.AH23	



B67875878

either adapter
will work fine

B67876131

